



## END-OF-SALE ANNOUCEMENT

### OVERVIEW

<b>DATE ISSUED:</b>	Feb 28, 2017
<b>ISSUED BY:</b>	Sierra Wireless Enterprise Solutions Product Management
<b>PRODUCTS AFFECTED:</b>	LS300 Series Gateways
<b>ORDER CODES AFFECTED:</b>	LS300 Gateways - <b>AT&amp;T</b> and <b>CANADA</b> variants
<b>FOR DISTRIBUTION TO:</b>	General Distribution
<b>SUMMARY:</b>	<p>Sierra Wireless announces the end-of-sale date and last ship date for LS300 (AT&amp;T and CANADA variants) Series Gateways. This notice contains all relevant milestones and dates for the affected products.</p> <p>The AirLink ® RV50 and ES450 are available as a functional replacement for LS300.  <a href="http://www.sierrawireless.com/rv50">www.sierrawireless.com/rv50</a>, <a href="http://www.sierrawireless.com/es450">www.sierrawireless.com/es450</a>)</p>

### PRODUCTION MILESTONES

<b>AFFECTED MODELS:</b>	LS300 ( <b>AT&amp;T</b> and <b>CANADA</b> variants)
<b>END OF SALE DATE:</b>	<b>30-APR-2017</b> The product cannot be ordered from Sierra Wireless after this date.
<b>LAST SHIP DATE:</b>	<b>30-DEC-2017</b> The last possible ship date that can be requested from Sierra Wireless.
<b>REASON:</b>	Component obsolescence

<b>MODELS:</b>	LS300 ( <b>VERIZON/SPRINT</b> and <b>ROW</b> variants)
<b>STATUS:</b>	Remain in production

### PRODUCT SUPPORT AND MAINTENANCE

<b>ACTIVE SOFTWARE MAINTENANCE PHASE:</b>	<b>FROM 30-APR-2017 TO 31-DEC-2017</b> During this phase, device software will be actively maintained. Software releases will contain bug fixes and security patches only, no new features will be deployed. Following Active Software Maintenance the products move to Critical Software Maintenance (see below).
<b>CRITICAL SOFTWARE MAINTENANCE PHASE:</b>	<b>FROM 1-JAN-2018 TO 31-DEC-2019</b> During this phase, new device software will be released if a Critical software issue or security vulnerability is discovered.

	<p>A software issue is deemed to be Critical if it causes the Sierra Wireless product or service to become systemically unavailable or unresponsive, and there is no available resolution or workaround.</p> <p>A security vulnerability is deemed to be Critical if it scores 9 or 10 on the Common Vulnerability Scoring System Version 3.0 (CVSSv3) as determined by Sierra Wireless.</p>
<b>END OF SOFTWARE MAINTENANCE:</b>	<b>31-DEC-2019</b> No new device software will be released after this date.

## CONTACT

<b>SALES:</b>	<a href="http://www.sierrawireless.com/sales">www.sierrawireless.com/sales</a> 1-877-687-7795
<b>CUSTOMER SUPPORT:</b>	<a href="http://www.sierrawireless.com/support">www.sierrawireless.com/support</a>

## REVISION HISTORY

<b>FEB 22, 2017</b>	Rev1: Initial announcement
---------------------	----------------------------

## AFFECTED PART NUMBERS

<b>PART No.</b>	<b>MODEL DESCRIPTION</b>	<b>SUGGESTED REPLACEMENT</b>	<b>PART No.</b>
<b>1101428</b>	LS300 (HSPA+, AT&T, AC)	RV50 (LTE/HSPA+, NA, DC)	<b>1102555</b>
<b>1101491</b>	LS300 (HSPA+, AT&T, DC)	ES450 (LTE/HSPA+, AT&T, AC)	<b>1102384</b>
<b>1101999</b>	LS300 (HSPA+, CANADA, AC)	RV50 (LTE/HSPA+, NA, DC)	<b>1102555</b>
<b>1102000</b>	LS300 (HSPA+, CANADA, DC)	ES450 (LTE/HSPA+, NA GENERIC, AC)	<b>1102386</b>